




























































REPLACEMENT IDLER TIRES FOR IDLERS & PULLIES

<p>IT - 56</p>  <p>AIWA</p>	<p>IT - 47</p> <p>USED IN: IW-8 IW-9</p>  <p>JVC PU51380A-2 PU55373</p>	<p>IT - 16</p> <p>USED IN: IW-47</p>  <p>PANASONIC VXLS0081, VXP0434 RCA 152422</p>	<p>IT - 51</p>  <p>JVC PU51250</p>	<p>IT - 58</p> <p>USED IN: IW-118</p>  <p>SONY X-4920-346-1</p>
<p>IT - 55</p>  <p>ZENITH, NEC N-895 JVC PU57658B-3/B-4/B-6 PU55822A-4/A-8</p>	<p>IT - 59</p>  <p>ROTEL SHERWOOD, KENWOOD</p>	<p>IT - 54</p>  <p>NAKAMICHI CAR DECK OC80635</p>	<p>IT - 27</p> <p>USED IN: IW-43</p>  <p>mitsubishi 522P00201</p>	<p>IT - 57</p>  <p>SANYO SANSUI</p>
<p>IT - 19</p> <p>USED IN: IW-58</p>  <p>HITACHI 6861505</p>	<p>IT - 12</p> <p>USED IN: IW-15</p>  <p>RCA 150650 HITACHI 6861481 & 6861482</p>	<p>IT - 41</p> <p>USED IN: IW-7</p>  <p>JVC PU51402A</p>	<p>IT - 9</p> <p>USED IN: IW-13 IW-14</p>  <p>SANYO/ 143-0-662T-01201 FISHER 143-0-662T-10350 143-0-741T-20001</p>	<p>IT - 5</p>  <p>PANASONIC VXPG0075</p>
<p>IT - 6</p>  <p>PANASONIC VXP0213 VXP0243 RCA 144265</p>	<p>IT - 17</p>  <p>MITSUBISHI 522B01701</p>	<p>IT - 42</p>  <p>MITSUBISHI 641B101020 EMERSON</p>	<p>IT - 32</p> <p>USED IN: IW-40, IW-41</p>  <p>JVC PU56043-1-4 PU56044-1-4</p>	<p>IT - 25</p> <p>USED IN: IW-25</p>  <p>SANYO/ 143-0-5470-00200 FISHER 143-0-551T-01400 SONY X-3653-315-0 A-6706-348-B</p>
<p>IT - 24</p>  <p>TOSHIBA 70316057 70326449</p>	<p>IT - 36</p> <p>USED IN: IW-45</p>  <p>JVC PU55374-3-8</p>	<p>IT - 44</p> <p>USED IN: IW-53</p>  <p>SAMSUNG 5253-701-1105V</p>	<p>IT - 10</p> <p>USED IN: IW-5</p>  <p>SANYO/ FISHER 143-0-4204-00400</p>	<p>IT - 26</p> <p>USED IN: IW-26</p>  <p>SHARP NPLYV0107GEZZ NPLYV0103GEZZ</p>

REPLACEMENT IDLER TIRES FOR IDLERS & PULLIES

<p>IT - 1 USED IN: IW-1</p>  <p>RCA 164113 HITACHI 6886971</p>	<p>IT - 23 USED IN: IW-6</p>  <p>JVC PU48967B KENWOOD, SANSUI</p>	<p>IT - 34 USED IN: IW-44</p>  <p>MITSUBISHI 522A002010</p>	<p>IT - 35</p>  <p>JVC PU58645-1-4</p>	<p>IT - 21 USED IN: IW-32, IW-52</p>  <p>SANYO/ 143-0-662T-15620 FISHER 143-0-662T-15621 613-037-4905</p>
<p>IT - 31 USED IN: IW-50</p>  <p>RCA 150614 HITACHI 6861471</p>	<p>IT - 28 USED IN: IW-28</p>  <p>SANYO/FISHER 143-0-4204-00700</p>	<p>IT - 46</p>  <p>HITACHI 6413111, 6413114</p>	<p>IT - 29 USED IN: IW-51</p>  <p>RCA 192242 SAMSUNG 6052-600-3101V</p>	<p>IT - 2 USED IN: IW-21</p>  <p>PANASONIC VXP0171 / 0174 RCA 144262 & 144263</p>
<p>IT - 40 USED IN: IW-18</p>  <p>PANASONIC VXPS0116</p>	<p>IT - 38 USED IN: IW-16</p>  <p>RCA 158190 HITACHI 6876043, 6876045</p>	<p>IT - 52 USED IN: IW-64</p>  <p>DAEWOO 97SA507200</p>	<p>IT - 37 USED IN: IW-46</p>  <p>PANASONIC VXP0292</p>	<p>IT - 39</p>  <p>SAMSUNG 5153-600-0114V</p>
<p>IT - 49</p>  <p>AKAI MZ-366-960J1</p>	<p>IT - 3 USED IN: IW-2 WITH LARGE WHEEL</p>  <p>PANASONIC VXP0521 VXPS0069 GOLDSTAR 321-149B</p>	<p>IT - 53 USED IN: IW-2 WITH SMALL WHEEL</p>  <p>PANASONIC VXP0521 WITH SMALL WHEEL</p>	<p>IT - 45 USED IN: IW-55</p>  <p>SANYO / 143-0-662T-14730 FISHER 613-037-4875</p>	<p>IT - 30 USED IN: IW-39, IW-17</p>  <p>GOLDSTAR, EMERSON, SAMSUNG 9000-250-3308V</p>
<p>IT - 11 USED IN: IW-10</p>  <p>SANYO/ FISHER 143-0-4204-00100</p>	<p>IT - 14 USED IN: IW-4</p>  <p>SHARP NIDL0006GEZZ</p>	<p>IT - 7 USED IN: IW-22</p>  <p>PANASONIC VXP0331/0433 RCA 152683</p>	<p>IT - 50</p>  <p>PANASONIC VXP0401</p>	<p>IT - 18 USED IN: IW-27</p>  <p>TOSHIBA 70326538 MODEL 5000, 5010, 5100 5120, 5200, 5320, 5600, 5800</p>

REPLACEMENT IDLER TIRES FOR IDLERS & PULLIES

IT - 22 USED IN: IW-60 IW-30  N.E.C. 161-781-79 AKAI BLB-353110	IT - 15 USED IN: IW-20  PANASONIC VXPS0054 RCA 155739	IT - 4 USED IN: IW-23  PANASONIC VXP0344 RCA 148580	IT - 13 USED IN: IW-3  SHARP NIDL0005GEZZ	IT - 43 USED IN: IW-49  PANASONIC VXP0463
IT - 8 USED IN: IW-24  PANASONIC VXP0329 RCA 152674	IT - 33 USED IN: IW-42  SHARP NPLYV0051GEZZ	IT - 20  SANYO/ 143-0-4104-00100 FISHER 143-0-4104-00200	IT - 48  JVC PU48907D PU48907E	

IT & IW CROSS REFERENCE BY MAKER PN.

Part #	IT#Used	IW#	Part #	IT#Used	IW#	Part #	IT#Used	IW#	Part #	IT#Used	IW#
AKAI			PU56044-1-4	IT-32	IW-41	RCA			143-0-662T-01201	IT-9	IW-13
BL-B-353110	IT-22	IW-60	PU58645-1-4	IT-35	-----	144262	IT-2	-----	143-0-662T-10350	IT-9	-----
MZ-366-960J1	IT-49	-----	MITSUBISHI			144265	IT-2	IW-21	143-0-662T-14730	IT-45	IW-55
DAEWOO			522A00201	IT-34	IW-44	148580	IT-6	-----	143-0-662T-15620	IT-21	IW-32
97SA507200	IT-52	IW-64	522B01701	IT-17	-----	150614	IT-4	IW-23	143-0-662T-15621	IT-21	IW-52
GOLDSTAR			522P00201	IT-27	IW-43	150614	IT-31	IW-50	143-0-741T-20001	IT-9	IW-14
321-149B	IT-3	-----	641B101020	IT-42	-----	150650	IT-12	IW-15	613-037-4875	IT-45	IW-55
HITACHI			N.E.C.			152422	IT-16	-----	613-037-4905	IT-21	IW-52
6413111	IT-46	-----	161-781-79	IT-22	IW-30	152674	IT-8	IW-24	SHARP		
6413114	IT-46	-----	PANASONIC			152683	IT-7	IW-22	NIDL0005GEZZ	IT-13	IW-3
6861471	IT-31	IW-50	VXLS0081	IT-16	IW-47	155739	IT-15	IW-20	NIDL0006GEZZ	IT-14	IW-4
6861481	IT-12	-----	VXP0171	IT-2	-----	158190	IT-38	IW-16	NPLYV0051GEZZ	IT-33	IW-42
6861482	IT-12	IW-15	VXP0174	IT-2	IW-21	162662	IT-38	IW-16	NPLYV0103GEZZ	IT-26	-----
6875386	IT-38	IW-16	VXP0213	IT-6	-----	164113	IT-1	IW-1	NPLYV0107GEZZ	IT-26	IW-26
6876043	IT-38	IW-16	VXP0243	IT-6	-----	192242	IT-29	IW-51	SONY		
6876045	IT-38	IW-16	VXP0292	IT-37	IW-46	SAMSUNG			A-6706-348-B	IT-25	-----
6886971	IT-1	IW-1	VXP0329	IT-8	IW-24	5153-600-0114V	IT-39	-----	X-3653-315-0	IT-25	IW-25
JVC			VXP0331	IT-7	IW-22	6052-600-3101V	IT-29	IW-51	X-4920-346-1	IT-58	IW-118
PU48907D	IT-48	-----	VXP0344	IT-4	IW-23	9000-250-3308V	IT-30	IW-39	TOSHIBA		
PU48907E	IT-48	-----	VXP0401	IT-50	-----	PULLEY	IT-30	IW-17	70316057	IT-24	-----
PU48967B	IT-23	IW-6	VXP0433	IT-7	-----	SANYO / FISHER			70326449	IT-24	-----
PU51250	IT-51	-----	VXP0434	IT-16	-----	143-0-4104-00100	IT-20	-----	70326538	IT-18	IW-27
PU51380A-2	IT-47	IW-8	VXP0463	IT-43	IW-49	143-0-4104-00200	IT-20	-----			
PU51402A	IT-41	IW-7	VXP0521 W/LG. WHEEL	IT-3	IW-2	143-0-4204-00100	IT-11	IW-10			
PU55373	IT-47	IW-9	VXP0521 W/SM. WHEEL	IT-53	IW-2	143-0-4204-00400	IT-10	IW-5			
PU55374-3-8	IT-36	IW-45	VXPG0075	IT-5	-----	143-0-4204-00700	IT-28	IW-28			
PU56043-1-4	IT-32	IW-40	VXPS0054	IT-15	IW-20	143-0-5470-00200	IT-25	-----			
			VXPS0069	IT-3	-----	143-0-551T-01400	IT-25	-----			
			VXPS0116	IT-40	IW-18						