

VERY IMPORTANT INSTALLATION INSTRUCTIONS

A wrist strap for discharging static electricity from your body is strongly recommended. Your work should be completed on a static discharge sheet on your workbench, to drain static electricity from the area. Be careful not to let your clothes touch the laser, as static electricity on clothing is not drained by the wrist strap.

The pins of the laser are short-circuited for protection during shipping and installation. To open the short-circuit, the following solder point must be de-soldered quickly at installation with a soldering iron whose insulation resistance to ground is greater than 10 meg-ohms.

